



Photo Point 7. View of unnamed tributary of Escondido Creek south of Kauana Loa Drive (16 June 2005).



Photo Point 8. Road culvert for the unnamed tributary of Escondido Creek west of Harmony Grove Road (16 June 2005).



Photo Point 9. Road culvert for unnamed tributary of Escondido Creek east of Harmony Grove Road (16 June 2005).



Photo Point 10. View of unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 11. Second location along unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 12. Third location along the unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 13. Fourth location along the unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 14. Fifth location along unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 15. Sixth location along unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 16. Seventh location along unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 17. Eighth location along unnamed tributary of Escondido Creek between Harmony Grove Road and Escondido Creek (16 June 2005).



Photo Point 18. Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 19. Second location along Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 20. Third location along Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 21. Forth location of Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 22. Dry secondary channel of Escondido Creek upstream of the confluence with unnamed tributary (16 June 2005).



Photo Point 23. Homeless encampment in *Arundo* on a sandy bank along Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 24. Second location of dry secondary channel of Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 25. Third location of dry secondary channel of Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 26. Fifth location of Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).



Photo Point 27. Sixth location of Escondido Creek upstream of confluence with unnamed tributary (16 June 2005).




Photo Point 28. Escondido Creek down stream of confluence with unnamed tributary (16 June 2005).



Photo Point 29. Second location of Escondido Creek down stream of confluence with unnamed tributary (16 June 2005).



Photo Point 30. Third location of Escondido Creek down stream of confluence with unnamed tributary (16 June 2005).



Photo Point 31. Escondido Creek in the vicinity of Country Club Road located approximately 0.8 mile down stream from the confluence of unnamed tributary (16 June 2005).



Photo Point 32. Second location along Escondido Creek in the vicinity of Country Club Road located approximately 0.8 mile down stream from the confluence of unnamed tributary (16 June 2005).



Photo Point 33. Third location along Escondido Creek in the vicinity of Country Club Road located approximately 0.9 mile down stream from the confluence of unnamed tributary (16 June 2005).



Photo Point 34. Fourth location along Escondido Creek located approximately 0.9 mile down stream from confluence with unnamed tributary. View is upstream from the Country Club Road crossing (16 June 2005).



Photo Point 35. Fifth location along Escondido Creek approximately 0.9 mile down stream from the confluence with unnamed tributary. View is downstream from the Country Club Road crossing (16 June 2005).